

## 83–602 Preparation for testing, connecting adapter to volt/ohm measuring instrument

---

### Preparation for test

---


- 1 Remove glove box (68–140).

### Connecting adapter to volt/ohm measuring instrument

---

- 2 Pull 12-point plug from electronic switching unit (9) for temperature control and connect to adapter. Yellow test card (issue October 1980) must be used.

9 Electronic control unit for temperature control



- 3 Connect adapter with volt/ohm measuring instrument to 12-point coupling and switch adapter to test step 1.

